Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-5066**

Resource Identification

Property Name(s): ..... Ms. Nelms Property {Current}
Property Date: ..... ca 1918
Address(s): ..... 13101 Old Suffolk Road {Current}
County/Independent City: Isle Of Wight
City: .....
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR
Surrounding area: ..... Rural

National Register Eligibility Status
Property is Historic (50 years or older)

Property has been recommended Not Eligible for listing

Resource Description

Ownership Status: ..... Private

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Central interior	Brick	Chimneys - Common Bond
Foundation	Foundation - Piers	Brick	Foundation - Common Bond
Porch	Porch - 1-story, 3-bay	Wood	Porch - Column(s)
Roof	Roof - Hipped	Tin	Roof - Pressed Shingle
Structural System	Structural System - Frame	Wood	Structural System - Weatherboard
Windows	Windows - Double-hung	Wood	Windows - 4/4

Site Description: ..... This house is located in a rural area and is well maintained. Ms. Nelms is 93 years old and has lived in the immediate area her entire life.

Secondary Resource Desc: There are three outbuildings associated with this house.

WUZIT Count:

No.	Wuzit Types	Historic?
1	House	Historic
2	Barn	Historic
1	Shed	Historic

NR Resource Count:

Report generated 1/18/05

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight **DHR Id#: 046-5066**

Individual Resource Information

WUZiT: ..... Shed

Est. Date of Construction:	1918 ca {Owner/site visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: North of the house is a wooden shed with a gabled roof.

WUZiT: ..... Barn

Est. Date of Construction:	1918 ca {Owner/site visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: North of the house is a barn barn (B) with a weather board exterior and a gabled roof flanked by shed-roofed additions clad in standing-seam metal

WUZiT: ..... Barn

Est. Date of Construction:	1918 ca {Owner/site visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: North of the house is a barn (A) with a weatherboard exterior and gable of hipped roof clad in standing-seam metal.

WUZiT: ..... House

Est. Date of Construction:	1918 ca {Owner/site visit}	*Accessed?*	No
Primary Resource?	Yes	*Number of Stories:*	2.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: Built c. 1918, this two-story Frame Vernacular style house features a wooden frame structural system that rests on brick piers. The exterior is covered in weatherboard and the hipped roof is clad in pressed tin. This house features a front facing gable with a wide band of trim that forms a pediment. Fenestration consists of two-over-two and four-over-four wooden double-hung sash windows. There are two brick chimneys. One chimney is situated on the central interior portion of the main roof and the other is located in the center of the gabled-rear addition. The porch is one-story in height and spans the entire width of the house. The porch also features wooden columns and a metal awning. A gabled addition has been appended to the north elevation of the house.

Cemetery Information

Bridge Information

National Register Eligibility Information *(Intensive Level Survey)*

Historic Context(s): ..... Domestic

Historic Time Period(s): ..... R- World War I to Present (1914 - Present)

Significance Statement: Though this house is currently in good condition, its design is common for the period of construction. This resource has no apparent association with any event or person important in our nation's history, lacks architectural significance, and does not appear to have the ability to yield important information. The resource is recommended as not eligible for the NRHP under Criteria A, B, C, or D.

Bibliographic Documentation

Reference #: 1
Bibliographic RecordType: ..... Survey
Author: ..... CCR, Inc.
Citation Abbreviation: .....
Notes: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

Ownership Information

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
35mm B&W	5	VDHR	2004/07/01	Single Dwelling

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: ..... Phase I Survey
Date: 2004/08/31
Organization or Person: ..... CCR, Inc.
VDHR Project ID # Associated with Event: .. 2002-1760
CRM Event Notes or Comments: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

CRM Event # 2,
Cultural Resource Management Event: ..... DHR Staff: Not Eligible
Date: 2004/11/18
Organization or Person: .....
VDHR Project ID # Associated with Event: . 2002-1760
CRM Event Notes or Comments: .....